

For H's

113105, 113106, 113107

FIELD SERVICE REPORT			
Date: 10/14/2021	Unit/Area:39	Identifier-i.e. Pos. # T-3910, X-3911 and V-3911	Decon Tracking Number: <u>2114, 2117</u>
Quantity: 3	For: _____ Repair _____ Warranty Repair _____ Replace _____ Evaluate _____ Update Other: <u>Sale</u> <input checked="" type="checkbox"/>		
Equipment Description: (Mfg., Model, P/N, Size, Material, etc.) T-3910 Distillation Column, X-3910 Column Condenser, V-3911 Reflux Separator			
Serial No. : See below			
Last Chemical Used in Equipment:: PC Oil, cumene			
MSDS Attached: PC Oil, cumene	MSDS Not Required:	Decontamination Not Required:	
Decontaminated by: <u>Shannon DeFord.</u> Printed Name			
Method of Decon: <u>Water flush, Steamed Clean.</u>			
Additional Information: (Describe problem, suspected cause of failure, vibration, service conditions, installation date, recommendations, etc., PLEASE BE COMPLETE).			
Installation date: 2001, No failure of equipment. Sold to reseller after decontamination of equipment.			
T-3910 Serial Number: AHE695 (Alabama Heat Exchangers)			
X-3910 Serial Number: Sheco 00-325 (Sheco)			
V-3911 Serial Number: 20-033 (Coastal Industrial Fabricators)			
Note: (1) Field decontamination has been performed in accordance with established procedures; However, disassembly of equipment may expose inaccessible cavities containing chemicals. Review MSDS for environmental and personal protective measures. (2) Vendor to supply list of parts and suspected cause of failure.			
Authorized Releasing Signature: Supervisor/Lead <u>Shannon DeFord</u> <u>Richard Spitzer</u>			Extension: <u>3085</u>
Authorized Receiving Signature: Stores <u>Dave B</u>			Extension: <u>3088</u>